

Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218



Policy # 6308271183

Ins Claim # F300301218



25

Closet area in dressing area



26

Garden tub and tile steps in master bathroom

Photo No. 21

Photo Sheet

Insured Borden, Jonathan

Document 23-3

Filed 12/16/2005

Claim #

F300301218

Policy #

6308271183

Ins Claim #

F300301218

51


Attic storage, insulation in walls



52


Plywood decking on floor of attic storage area

Photo No. 22



53

Damage to rafters from attic storage area



54


View: Damage to 2 x 8 rafters from attic storage area

Photo No. 23



55

View: Attic storage and insulation



56

Damage to rafters

Photo No. 24

Photo Sheet

Insured Borden, Jonathan

Case 1:04-cv-00174-SJM

Document 23-3

Filed 12/16/2005


Page 5 of 20

Coverage BLDG

Claim # F300301218



Policy # 6308271183

Ins Claim # F300301218



63

Wallpaper in upstairs hallway bathroom



64

Foyer

Photo No. 25


Insured Borden, Jonathan

Coverage BLDG



67

Foyer towards guest bedroom area



68

Foyer towards front entry and steps up to second level

Photo No. 26

Insured Borden, Jonathan

Coverage BLDG

75

Living room fireplace and hearth

PITTSBURGH
MAY 07 2003



76

Living room ceiling and stencil on walls




Photo No. 27

Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218


Policy # 6308271183

Ins Claim # F300301218



77

Outside wall of living room



78

Living room drywall between living room and den


Photo No. 28

Insured Borden, Jonathan



79

Bay window area boarded up on rear elevation of dwelling located in living room



80

View: Living room towards foyer

Photo No. 29



Insured Borden, Jonathan

Coverage BLDG



81

Jacuzzi room located on rear right
end of dwelling



82

Carpet in Jacuzzi room

Photo No. 30

Photo Sheet


Insured Borden, Jonathan

Document 23-3

Filed 12/16/2005

Page 11 of 20


Claim # F300301218
Policy # 0306271183
Ins Claim # F300301218



83

View: Jacuzzi room

PICTURE
MAY 07 2003
Ans.



84

Jacuzzi with tile surround

Photo No. 31

Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218


Policy # 6308271183

Ins Claim # F300301218



115

Closet in playroom



116

Den and collapsed flooring

Photo No. 32

Insured Borden, Jonathan


Coverage BLDG

Claim # 510201218
Policy # 6308271183
Ins Claim # F300301218



117

Den



118

Den wallpaper

Photo No. 33


Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218


Policy # 6308271183

Ins Claim # F300301218



119

Ceiling fallen in den



120

Wallpaper and wall framing between den and kitchen

Photo No. 34

Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218

Policy # 6308271183

Ins Claim # F300301218



121

Ceiling and recessed lights in den

PITTSBURGH
MAY 07 2003
Ans. _____



122

View: Floor collapsed in den

Photo No. 35

Photo Sheet

Case 1:04-cv-00175-SJM

Document 23-3

Filed 12/16/2005

Page 16 of 20

Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218


Policy # 6308271183

Ins Claim # F300301218



123

Den flooring collapsed into basement



124

Den

Photo No. 36

Photo Sheet

Case 1:06-cv-00175-SJM

Document 23-3

Filed 12/16/2005

Page 17 of 20

Class # F300301218

Policy # 6308271183

Ins Claim # F300301218


Insured Borden, Jonathan

Coverage BLDG



126

Formal dining room



127

Formal Dining Room

Photo No. 37

Photo Sheet

Insured Borden, Jonathan

Case 1:04-cv-00175-SJM

Document 23-3

Filed 12/16/2005

Page 18 of 20

Coverage BLDG

Claim # F300301218


Policy # 6308271183

Ins Claim # F300301218



128

Formal Dining Room



129

Formal Dining Room


Photo No. 38

Insured Borden, Jonathan

Coverage BLDG

132

Kitchen



133

Kitchen



Photo No. 39

Photo Sheet

Insured Borden, Jonathan

Case 1:04-cv-00175-SJM

Document 23-3

Filed 12/16/2005

Page 20 of 20

Coverage BLDG

Claim # F300301218

Policy # 6308271183


Ins Claim # F300301218



134

Kitchen

PT. SUMMIT
MAY 07 2003
Ans.



135

Kitchen

Photo No. 40